

| No | Type | Activation Bluetooth connection with device key | Phone s REDIAL activation | Access to mobile phone voice-dial function (voice tags) | Possibility to switch car kit / private mode with Bluetooth device / phones keys | A2DP supported | Version of phone software used to test/ Comments |
|----|------------------------------|---|---------------------------|---|--|----------------|--|
| 1 | Apple iPhone | ✓ | ✓ | | ✓ | | 3.0(7a341) |
| 2 | Apple iPhone 3G | ✓ | ✓ | | ✓ | ✓ | 4.2.1 (8a306) |
| 3 | Apple iPhone 3GS | ✓ | ✓ | ✓ | ✓ | ✓ | 4.3.3 (16g4) |
| 4 | Apple iPhone 4 | ✓ | ✓ | ✓ | ✓ | ✓ | 4.3.1 (8g4) |
| 5 | BlackBerry 8120 Pearl | ✓ | ✓ | ✓ | ✓ | ✓ | v4.3.0.35 |
| 6 | BlackBerry 8310 Curve | ✓ | ✓ | ✓ | ✓ | | v4.2.2.146 |
| 7 | BlackBerry 8800 | ✓ | ✓ | ✓ | ✓ | | v4.2.1.101 |
| 8 | BlackBerry 8900 Curve | ✓ | ✓ | ✓ | ✓ | | v5.0.0.1036 |
| 9 | BlackBerry 9105 Pearl | ✓ | ✓ | ✓ | ✓ | ✓ | v5.0.0.696(platworm 6.2.0.57) |
| 10 | BlackBerry 9300 Curve 3G | ✓ | ✓ | ✓ | ✓ | | v5.0.0.716(platworm 6.3.0.13) |
| 11 | BlackBerry 9500 Storm | ✓ | ✓ | ✓ | ✓ | ✓ | v4.7.0.41 pl 4.0.0.40 |
| 12 | BlackBerry 8520 Curve | ✓ | ✓ | ✓ | ✓ | | v5.0.0.306 pl 4.2.0.113 |
| 13 | BlackBerry 9630 | ✓ | ✓ | ✓ | ✓ | ✓ | v4.7.1.20 pl 4.1.0.15 |
| 14 | BlackBerry 9700 Bold | ✓ | ✓ | ✓ | ✓ | ✓ | v5.0.0.979 |
| 15 | BlackBerry 9780 Bold | ✓ | ✓ | ✓ | ✓ | | v6.0.0.359 pl 6.5.0.93 |
| 16 | BlackBerry 9800 Torch | ✓ | ✓ | ✓ | ✓ | ✓ | v6.0.0.100 pl 6.4.0.47 |
| 17 | HTC 7 Mozart | ✓ | ✓ | ✓ | ✓ | ✓ | windows phone 7radio 5.50.09.18_22.24.50.09u |
| 18 | HTC Desire | ✓ | ✓ | | ✓ | ✓ | android os 2.2sw. nr. 2.12.110.4 |
| 19 | HTC Desire HD | ✓ | ✓ | | ✓ | ✓ | android os 2.3.3sw. nr. 2.36.405.8 |
| 20 | HTC Desire Z | ✓ | ✓ | ✓ | ✓ | ✓ | android os 2.2.1sw. nr. 1.72.405.2 |
| 21 | HTC Incredible S | ✓ | ✓ | ✓ | ✓ | ✓ | android os 2.2.1sw. nr. 1.36.405.1 |
| 22 | HTC Legend | ✓ | ✓ | | ✓ | ✓ | android os 2.1sw. nr. 1.23.161.1 |
| 23 | HTC Magic | ✓ | ✓ | | ✓ | | 1.5 |
| 24 | HTC T-Mobile G1 | ✓ | ✓ | | ✓ | ✓ | fw: 1.6 |
| 25 | HTC Hero / T-Mobile G2 Touch | ✓ | ✓ | | ✓ | ✓ | fw: 2.1update 13.31.111.1 |
| 26 | HTC Tattoo | ✓ | ✓ | | ✓ | | sw 1.67.405.6 |
| 27 | HTC Touch | ✓ | ✓ | ✓ | ✓ | ✓ | 1.11.405.18 wweradio 02.93.90 |
| 28 | HTC Touch2 | ✓ | ✓ | | ✓ | ✓ | 1.28.407.4 (66092) |
| 29 | HTC Touch 3G | ✓ | ✓ | ✓ | ✓ | | 2.32.407.2 (44800) |
| 30 | HTC Touch Cruise | ✓ | ✓ | ✓ | ✓ | ✓ | 3.13.407.0 ger |
| 31 | HTC Touch DIAMOND 2 | ✓ | ✓ | | ✓ | ✓ | radio 1.19.407.1 (51489) ger |
| 32 | HTC Touch Dual | ✓ | ✓ | ✓ | ✓ | ✓ | 1.31.407.09 |
| 33 | HTC HD mini | ✓ | ✓ | | ✓ | ✓ | rom: 1.36.479.1 (94538) wwe |
| 34 | HTC HD2 | ✓ | ✓ | | ✓ | | 1.43.111.2 (70315) ger |
| 35 | HTC Touch Pro | ✓ | ✓ | ✓ | ✓ | ✓ | 1.60.161.1 wwe |
| 36 | HTC Touch Pro2 | ✓ | ✓ | ✓ | ✓ | ✓ | radio 1.19.407.1 (51489) ger |
| 37 | HTC Wildfire | ✓ | ✓ | | ✓ | ✓ | android 2.2.12.24.162.1 |
| 38 | HTC S730 | ✓ | ✓ | ✓ | ✓ | ✓ | 1.31.407.0 |
| 39 | LG BL40 New Chocolate | ✓ | ✓ | | ✓ | ✓ | bl40-msm76xx-v10a-sep-21-2009-xx |
| 40 | LG GM750 | ✓ | ✓ | | ✓ | ✓ | v10b |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com



working



* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>



1 Only from phone



** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

| No | Type | Activation Bluetooth connection with device key | Phone s REDIAL activation | Access to mobile phone voice-dial function (voice tags) | Possibility to switch car kit / private mode with Bluetooth device / phones keys | A2DP supported | Version of phone software used to test/ Comments |
|----|------------------------|---|---------------------------|---|--|----------------|--|
| 41 | LG KG 810 | ✓ | ✓ | | ✓ | ✓ | kg810p64 eur v10g xxx-xx |
| 42 | LG KP500 Cookie | ✓ | ✓ | | ✓ | | kp500at_v10d |
| 43 | LG KU 990 | ✓ | ✓ | | ✓ | ✓ | ku990_v10b |
| 44 | Motorola DEFY (MB525) | ✓ | ✓ | ✓ | ✓ | | android 2.1-update1 |
| 45 | Motorola Milestone 2 | ✓ | ✓ | ✓ | ✓ | ✓ | android 2.2nk: mils2_u6_2.2.16 |
| 46 | Motorola RAZR V3xx | ✓ | ✓ | | ✓ | ✓ | r26111ld_u_96.67.32r |
| 47 | Motorola RAZR V3 | ✓ | ✓ | ✓ | ✓ | | r374_g_0e40.3cr |
| 48 | Nokia 2323 classic | ✓ | ✓ | | ✓ | | v 06.46 |
| 49 | Nokia 2330 classic | ✓ | ✓ | | ✓ | | v 06.46 |
| 50 | Nokia 2700 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v 09.97 |
| 51 | Nokia 2730 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v 10.45 |
| 52 | Nokia 3109c | ✓ | ✓ | ✓ | ✓ | | v07.21 |
| 53 | Nokia 3120 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v 10.00 |
| 54 | Nokia 3710 fold | ✓ | ✓ | ✓ | ✓ | ✓ | v09.73 |
| 55 | Nokia 3720 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v10.16 |
| 56 | Nokia 5200 | ✓ | ✓ | ✓ | ✓ | | v07.20 |
| 57 | Nokia 5230 | ✓ | ✓ | ✓ | ✓ | ✓ | v 40.0.003 |
| 58 | Nokia 5310 XpressMusic | ✓ | ✓ | ✓ | ✓ | ✓ | v09.42 |
| 59 | Nokia 5500 | ✓ | ✓ | ✓ | ✓ | | v 04.60 |
| 60 | Nokia 5530 XpressMusic | ✓ | ✓ | ✓ | ✓ | ✓ | v 11.0.054 |
| 61 | Nokia 5630 XpressMusic | ✓ | ✓ | ✓ | ✓ | ✓ | v 012.008 |
| 62 | Nokia 5700 | ✓ | ✓ | ✓ | ✓ | ✓ | v 03.83.1 |
| 63 | Nokia 5730 XpressMusic | ✓ | ✓ | ✓ | ✓ | ✓ | 100.48.122 |
| 64 | Nokia 5800 XpressMusic | ✓ | ✓ | ✓ | ✓ | ✓ | v 51.0.006 |
| 65 | Nokia 6103 | ✓ | ✓ | ✓ | ✓ | | v04.90 |
| 66 | Nokia 6110 Navigator | ✓ | ✓ | ✓ | ✓ | ✓ | v06.01 |
| 67 | Nokia 6124c | ✓ | ✓ | ✓ | ✓ | ✓ | v04.34 |
| 68 | Nokia 6125 | ✓ | ✓ | ✓ | ✓ | | v05.43 |
| 69 | Nokia 6111 | ✓ | ✓ | ✓ | ✓ | | v03.82 |
| 70 | Nokia 6210 Navigator | ✓ | ✓ | ✓ | ✓ | ✓ | v05.16 |
| 71 | Nokia 6220 Classic | ✓ | ✓ | ✓ | ✓ | ✓ | v04.13 |
| 72 | Nokia 6230i | ✓ | ✓ | ✓ | ✓ | | v03.89 |
| 73 | Nokia 6233 | ✓ | ✓ | ✓ | ✓ | | v05.60 |
| 74 | Nokia 6234 | ✓ | ✓ | ✓ | ✓ | | v05.60 |
| 75 | Nokia 6270 | ✓ | ✓ | ✓ | ✓ | | v03.81 |
| 76 | Nokia 6288 | ✓ | ✓ | ✓ | ✓ | | v06.43 |
| 77 | Nokia 6300 | ✓ | ✓ | ✓ | ✓ | | v 07.21 |
| 78 | Nokia 6300i | ✓ | ✓ | ✓ | ✓ | | v04.93 |
| 79 | Nokia 6303 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v 10.12 |
| 80 | Nokia 6303i classic | ✓ | ✓ | ✓ | ✓ | ✓ | v 07.10 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com



working



* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>



1 Only from phone



** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

| No | Type | Activation Bluetooth connection with device key | Phone s REDIAL activation | Access to mobile phone voice-dial function (voice tags) | Possibility to switch car kit / private mode with Bluetooth device / phones keys | A2DP supported | Version of phone software used to test/ Comments |
|-----|----------------------|---|---------------------------|---|--|----------------|--|
| 81 | Nokia 6500c | ✓ | ✓ | ✓ | ✓ | ✓ | v 09.48 |
| 82 | Nokia 6600i Slide | ✓ | ✓ | ✓ | ✓ | ✓ | v 36.16 |
| 83 | Nokia 6650 fold | ✓ | ✓ | ✓ | ✓ | | v 03.31 |
| 84 | Nokia 6700 classic | ✓ | ✓ | ✓ | ✓ | ✓ | v13.21 |
| 85 | Nokia 6710 Navigator | ✓ | ✓ | ✓ | ✓ | ✓ | 031.022 |
| 86 | Nokia 6720 classic | ✓ | ✓ | ✓ | ✓ | ✓ | 031.022 |
| 87 | Nokia 6760 slide | ✓ | ✓ | ✓ | ✓ | ✓ | v 03.38 |
| 88 | Nokia 7900 Prism | ✓ | ✓ | ✓ | ✓ | ✓ | v04.84 |
| 89 | Nokia 8600 Luna | ✓ | ✓ | ✓ | ✓ | | v04.04 |
| 90 | Nokia 8800 | ✓ | ✓ | ✓ | ✓ | | v04.10 |
| 91 | Nokia C1-01 | ✓ | ✓ | | ✓ | ✓ | v 04.40 |
| 92 | Nokia C1-02 | ✓ | ✓ | | ✓ | | v 04.40 |
| 93 | Nokia C3-00 | ✓ | ✓ | | ✓ | ✓ | v 08.63 |
| 94 | Nokia C5 | ✓ | ✓ | ✓ | ✓ | ✓ | v031.022 |
| 95 | Nokia C7-00 | ✓ | ✓ | ✓ | ✓ | ✓ | v 013.016 |
| 96 | Nokia E7-00 | ✓ | ✓ | ✓ | ✓ | ✓ | v 013.016 |
| 97 | Nokia E50 | ✓ | ✓ | ✓ | ✓ | | v07.36.0.0 |
| 98 | Nokia E52 | ✓ | ✓ | ✓ | ✓ | ✓ | 053.001 |
| 99 | Nokia E55 | ✓ | ✓ | ✓ | ✓ | ✓ | 034.001 |
| 100 | Nokia E60 | ✓ | ✓ | ✓ | ✓ | ✓ | v 3.0633.09.04 |
| 101 | Nokia E61i | ✓ | ✓ | ✓ | ✓ | ✓ | v 3.0633.69.00 |
| 102 | Nokia E66 | ✓ | ✓ | ✓ | ✓ | ✓ | v 200.21.118 |
| 103 | Nokia E70 | ✓ | ✓ | ✓ | ✓ | ✓ | v3.0633.09.04 |
| 104 | Nokia E71 | ✓ | ✓ | ✓ | ✓ | ✓ | 500.21.009 |
| 105 | Nokia E72 | ✓ | ✓ | ✓ | ✓ | ✓ | 053.001 |
| 106 | Nokia E75 | ✓ | ✓ | ✓ | ✓ | ✓ | 110.48.125 |
| 107 | Nokia E90 | ✓ | ✓ | ✓ | ✓ | ✓ | v300.34.84 |
| 108 | Nokia N8 | ✓ | ✓ | ✓ | ✓ | ✓ | v 014.002 |
| 109 | Nokia N70 | ✓ | ✓ | ✓ | ✓ | ✓ | v5.0705.3.0.1 |
| 110 | Nokia N76 | ✓ | ✓ | ✓ | ✓ | ✓ | v31.0.014 |
| 111 | Nokia N78 | ✓ | ✓ | ✓ | ✓ | ✓ | v30.011 |
| 112 | Nokia N79 | ✓ | ✓ | ✓ | ✓ | ✓ | v 20.175 |
| 113 | Nokia N82 | ✓ | ✓ | ✓ | ✓ | ✓ | v 31.0.016 |
| 114 | Nokia N85 | ✓ | ✓ | ✓ | ✓ | ✓ | v 31.002 |
| 115 | Nokia N86 8MP | ✓ | ✓ | ✓ | ✓ | ✓ | 21.006 |
| 116 | Nokia N95 | ✓ | ✓ | ✓ | ✓ | ✓ | v31.0.017 |
| 117 | Nokia N96 | ✓ | ✓ | ✓ | ✓ | ✓ | v30.033 |
| 118 | Nokia N97 | ✓ | ✓ | ✓ | ✓ | ✓ | v 22.0.110 |
| 119 | Nokia N97 mini | ✓ | ✓ | ✓ | ✓ | ✓ | v 12.0.110 |
| 120 | Nokia N900 | ✓ | ✓ | | ✓ | ✓ | 20.210.36.2 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com



working



* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>



1 Only from phone



** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

| No | Type | Activation Bluetooth connection with device key | Phone s REDIAL activation | Access to mobile phone voice-dial function (voice tags) | Possibility to switch car kit / private mode with Bluetooth device / phones keys | A2DP supported | Version of phone software used to test/ Comments |
|-----|---------------------------------|---|---------------------------|---|--|----------------|--|
| 121 | Nokia X3 | ✓ | ✓ | ✓ | ✓ | ✓ | v 11.00 |
| 122 | Nokia X6 | ✓ | ✓ | ✓ | ✓ | ✓ | v 32.0.002 |
| 123 | Samsung B2700 | ✓ | ✓ | | ✓ | | b2700xxib2 |
| 124 | Samsung B3410 | ✓ | ✓ | | ✓ | | b3410xxik4 |
| 125 | Samsung B7330 OmniaPro | ✓ | ✓ | | ✓ | | b7330xxig2 |
| 126 | Samsung C6625 | ✓ | ✓ | | ✓ | | c6625buie1 |
| 127 | Samsung Vodafone 360 H1 (i8320) | ✓ | ✓ | | ✓ | ✓ | i8320buik1 |
| 128 | Samsung I8700 Omnia 7 | ✓ | ✓ | ✓ | ✓ | ✓ | windows phone 7radio sw:2424.10.10.3 |
| 129 | Samsung I9100 Galaxy S II | ✓ | ✓ | ✓ | ✓ | ✓ | i9100xwke1 |
| 130 | Samsung S3650 Corby | ✓ | ✓ | | ✓ | ✓ | s3650xxii3 |
| 131 | Samsung S5230 Avilla | ✓ | ✓ | | ✓ | ✓ | s5230bvie3 |
| 132 | Samsung S7220 | ✓ | ✓ | | ✓ | ✓ | s7220xxia2 |
| 133 | Samsung S8300V | ✓ | ✓ | | ✓ | ✓ | s8300buic6 |
| 134 | Samsung S8500 Wave | ✓ | ✓ | | ✓ | ✓ | s8500xxji4 |
| 135 | Samsung S8530 Wave II | ✓ | ✓ | | ✓ | ✓ | s8530xxjka |
| 136 | Samsung SGH-D800 | ✓ | | ✓ | | | d800xxfa2 |
| 137 | Samsung SGH-D840 | ✓ | | | | | d840xxgb3 |
| 138 | Samsung SGH-D880 | ✓ | ✓ | | ✓ | | d880xahb3 |
| 139 | Samsung SGH-E500 | ✓ | ✓ | ✓ | | | e500xafh7 |
| 140 | Samsung SGH-F210 | ✓ | | | ✓ | | f210xxgj1 |
| 141 | Samsung SGH-F300 | ✓ | ✓ | | ✓ | ✓ | f300xxgcg |
| 142 | Samsung SGH-F700v | ✓ | ✓ | | ✓ | ✓ | f700amgj8 |
| 143 | Samsung SGH-G600 | ✓ | ✓ | | ✓ | ✓ | g600xwge4 |
| 144 | Samsung SGH-G800 | ✓ | ✓ | | ✓ | ✓ | g80lakhb1 |
| 145 | Samsung SGH-L760V | ✓ | ✓ | | ✓ | ✓ | l760bugg1 |
| 146 | Samsung SGH-U700v | ✓ | ✓ | | ✓ | ✓ | u70bbhhb1 |
| 147 | Samsung SGH-U800 | ✓ | ✓ | | ✓ | ✓ | u800brhl1 |
| 148 | Samsung SGH-i200 | ✓ | ✓ | | ✓ | ✓ | i200achh1 |
| 149 | Samsung SGH-i550 | ✓ | | | ✓ | | i550akhe2 |
| 150 | Samsung SGH-i900 OMNIA 8GB | ✓ | ✓ | | ✓ | | i900xxib2 |
| 151 | Samsung SGH-X820 | ✓ | | | | | x820anff1 |
| 152 | Samsung Xcover 271 (B2710) | ✓ | ✓ | | ✓ | ✓ | b2710bojj3 |
| 153 | Sonim Land Rover S1 | ✓ | ✓ | | ✓ | | |
| 154 | Sonim XP1300 Core | ✓ | ✓ | | ✓ | | |
| 155 | Sonim XP3.20 Quest Pro | ✓ | ✓ | | ✓ | | |
| 156 | Sonim XP3300 Force | ✓ | ✓ | | ✓ | | |
| 157 | Sony Ericsson Aino | ✓ | ✓ | ✓ | ✓ | ✓ | r7ba084 |
| 158 | Sony Ericsson C702 | ✓ | ✓ | ✓ | ✓ | ✓ | r3aa054 |
| 159 | Sony Ericsson C902 | ✓ | ✓ | ✓ | ✓ | ✓ | r3ca038 |
| 160 | Sony Ericsson C903 | ✓ | ✓ | ✓ | ✓ | ✓ | r1ga028 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com



working



* Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>



1 Only from phone



** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list BURY EasyTouch

Updated: 2011-08-26 / v.03

Device software version: 17

| No | Type | Activation Bluetooth connection with device key | Phone s REDIAL activation | Access to mobile phone voice-dial function (voice tags) | Possibility to switch car kit / private mode with Bluetooth device / phones keys | A2DP supported | Version of phone software used to test/ Comments |
|-----|-----------------------------------|---|---------------------------|---|--|----------------|--|
| 161 | Sony Ericsson C905 | ✓ | ✓ | ✓ | ✓ | ✓ | r1da032 |
| 162 | Sony Ericsson Elm | ✓ | ✓ | ✓ | ✓ | ✓ | r7ca061 |
| 163 | Sony Ericsson G502 | ✓ | ✓ | ✓ | ✓ | ✓ | r1fa031 |
| 164 | Sony Ericsson G900 | ✓ | ✓ | ✓ | ✓ | ✓ | 1203-6566r9n002 |
| 165 | Sony Ericsson J105i Naite | ✓ | ✓ | ✓ | ✓ | ✓ | r1ha035 |
| 166 | Sony Ericsson K510i | ✓ | ✓ | ✓ | ✓ | | r4ch003 |
| 167 | Sony Ericsson K530i | ✓ | ✓ | ✓ | ✓ | ✓ | r8bb001 |
| 168 | Sony Ericsson K550i | ✓ | ✓ | ✓ | ✓ | ✓ | r8ba024 |
| 169 | Sony Ericsson K610i | ✓ | ✓ | ✓ | ✓ | ✓ | r1jg001 |
| 170 | Sony Ericsson K800i | ✓ | ✓ | ✓ | ✓ | | r8bf003 |
| 171 | Sony Ericsson K810i | ✓ | ✓ | ✓ | ✓ | ✓ | r1jf001 |
| 172 | Sony Ericsson S312 | ✓ | ✓ | | ✓ | ✓ | r1db002 |
| 173 | Sony Ericsson W205 | ✓ | ✓ | | ✓ | ✓ | r1ca001 |
| 174 | Sony Ericsson W395 | ✓ | ✓ | | | ✓ | r1fa012 |
| 175 | Sony Ericsson W580i | ✓ | ✓ | ✓ | ✓ | ✓ | r8be001 |
| 176 | Sony Ericsson W595i | ✓ | ✓ | ✓ | ✓ | ✓ | r3eg004 |
| 177 | Sony Ericsson W600i | | | | | | r7b046 |
| 178 | Sony Ericsson W610i | ✓ | ✓ | ✓ | ✓ | ✓ | r1jd001 |
| 179 | Sony Ericsson W660i | ✓ | ✓ | ✓ | ✓ | ✓ | r8bb001 |
| 180 | Sony Ericsson W705 | ✓ | ✓ | ✓ | ✓ | ✓ | r6bc003 |
| 181 | Sony Ericsson W810i | ✓ | ✓ | ✓ | ✓ | | r4ea031 |
| 182 | Sony Ericsson W850i | ✓ | ✓ | ✓ | ✓ | ✓ | r1ed001 |
| 183 | Sony Ericsson W890i | ✓ | ✓ | ✓ | ✓ | ✓ | r1fa035 |
| 184 | Sony Ericsson W910i | ✓ | ✓ | ✓ | ✓ | ✓ | r1ea030 |
| 185 | Sony Ericsson W960i | ✓ | ✓ | ✓ | ✓ | ✓ | r6g04 |
| 186 | Sony Ericsson W995 | ✓ | ✓ | ✓ | ✓ | ✓ | r1ha035 |
| 187 | Sony Ericsson Vivaz | ✓ | ✓ | ✓ | ✓ | ✓ | 1224-4699_r2ak006 |
| 188 | Sony Ericsson V800 | ✓ | ✓ | ✓ | ✓ | ✓ | r1j002 |
| 189 | Sony Ericsson XPERIA X1 | ✓ | ✓ | ✓ | ✓ | | r3aa013 |
| 190 | Sony Ericsson XPERIA X2 | ✓ | ✓ | | ✓ | ✓ | r1aa035 |
| 191 | Sony Ericsson XPERIA X8 | ✓ | ✓ | | ✓ | ✓ | android 2.1-update1 |
| 192 | Sony Ericsson XPERIA X10 mini | ✓ | ✓ | | ✓ | | android 1.6 |
| 193 | Sony Ericsson XPERIA X10 mini pro | ✓ | ✓ | | ✓ | ✓ | android 2.1-update1 |
| 194 | Sony Ericsson Yari | ✓ | ✓ | | ✓ | ✓ | r7ba084 |

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓ * Phonebook and call lists only from phone (with installed 2nd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet2nd>
- ✓ 1 Only from phone
- ✓ ** Phonebook and call lists only from phone (with installed 3rd Edition Applet for Nokia mobiles) <http://www.bury.com/en/applet3rd>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.